



Figure 18. A post-recovery photograph of the ADCP deployed at Site 5. The ADCP was deployed in a TRBM. As seen in this photo, the ADCP became significantly tilted (>25 degrees) while in the TRBM. Data from this ADCP could not be salvaged and is not included in this report.