

Figure 34. (A) A photograph of the tripod recovered from Site 3 at the end of the first deployment. All instruments experienced some biofouling. (B) A photograph of the ADCP mounted to the tripod shown in (A). Two of the transducers on the ADCP were biofouled (one significantly).

