



Figure 40. (A) Photograph of the tripod recovered from Site 6 at the end of the second deployment. Biofouling of the tripod surfaces and the surfaces of instruments was not significant. (B) Photograph of the ABS and (C) photograph of the ADV mounted to the tripod in (A).