



Figure 38. A photograph of the TRBM and ADCP recovered from Site 5 at the end of the second deployment. This instrument package was not recovered and cleaned at the end of the first deployment. The ADCP was therefore in the water for the entire 6-month duration. Biofouling of the ADCP during this time was significant. The ADCP also became tilted, which led to the complete loss of data at this site.