



Figure 46. A photograph of the tripod recovered from Site 8 at the end of the second deployment. The tripod surface and the surface of the AP are not significantly biofouled. However, upon removal of the hosiery (used to prevent biofouling), two of the three transducers on the AP were covered with mud.