



Figure 39. (A) Photographs of the tripod recovered from Site 6 at the end of the first deployment. The surfaces of the tripod and instruments are significantly biofouled. Photos of the barnacle-encrusted instruments are provided in (B) through (E).