



Figure 41. A photograph of the tripod recovered from Site 7A at the end of the first deployment. The surfaces of the tripod and all instruments on the tripod were heavily encrusted with biofouling.